Harris House 43 E. Broadway Bel Air private

Without its shingles, the Harris House would be a typical L-shaped house of the turn of the century. Two similar houses were built in 1899 on Roland Avenue. They have shiplap siding and fish scale shingles in the front gables and project a more formal appearance than does this house. The warm brown shingles, a 20th century addition, give it an air at once shaggy and informal. It does not put itself forward, but retreats to the privacy of its lot.

With the enormous popularity of the Shingle Style elsewhere in the Country, the wonder is that it did not catch on in Bel Air, but it did not. Some bungalows were built after World War I and a few houses were shingled, notably two on Broadway. Possibly the style, like that of the fully irregular Queen Anne, was too informal for Bel Air's

tastes.

### MARYLAND HISTORICAL TRUST

# INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

	lst	
	CONGRESSIONAL DISTRI	СТ
_ VICINITY OF	COLINTY	
_	Harford	
STATUS	PRESE	ENT USE
	AGRICULTURE	MUSEUM
UNOCCUPIED	COMMERCIAL	PARK
WORK IN PROGRESS	EDUCATIONAL	X PRIVATE RESIDENCE
ACCESSIBLE	ENTERTAINMENT	RELIGIOUS
X_YES: RESTRICTED	GOVERNMENT	SCIENTIFIC
YES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION_
_NO	MILITARY	_ <sub>OTHER:</sub> rental
on_& Reed	Telephone #: 838	
VICINITY OF	Maryland	
		21014
RIPTION	Liber #:	21014
RIPTION	Liber #:	21014
<b>RIPTION</b> Courthouse	Liber #: Folio #:	21014
	Folio #:	21014
	Folio #:	21014
Courthouse	Folio #:	21014
	Folio #:	21014
Courthouse	Folio #:	21014
Courthouse  FING SURVEYS	Folio #:  STATE  Maryland	
Courthouse  FING SURVEYS	Folio #:	
Courthouse  FING SURVEYS	Folio #:  STATE  Maryland	
	STATUS  XOCCUPIED  LUNOCCUPIED  WORK IN PROGRESS  ACCESSIBLE  YES: RESTRICTED  YES: UNRESTRICTED	CONGRESSIONAL DISTRI  VICINITY OF  COUNTY Harford  STATUS  X OCCUPIED  — UNOCCUPIED  — UNOCCUPIED  — WORK IN PROGRESS  ACCESSIBLE  X YES: RESTRICTED  — YES: UNRESTRICTED  — NO  CONTRESSIONAL DISTRICTED  — GOVERNMENT  — INDUSTRIAL  — MILITARY  CONTRESSIONAL DISTRICTED  — MILITARY  STATE, Z



HK-1361

CONDITION

**CHECK ONE** 

**CHECK ONE** 

 $\underline{\underline{X}}_{\text{GOOD}}$ 

\_\_FAIR

\_\_DETERIORATED

\_\_UNALTERED

X\_ORIGINAL SITE

\_\_UNEXPOSED

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This small, L-shaped, shingle house is at 43 E. Broadway, in the Town of Bel Air, Harford County, Maryland. According to a niece of a former owner, the shingles were added later. It is a two and a half story gable roofed house with its ell facing the street. A three part window occupies the front gable. It has a slender single pane flanked by 1/1 double-hung sash windows of the same proportion. The rest of the windows are 1/1 with a wooden lintel. A pair of these windows occupy the second story of the ell. The entrance is in the back building in the west elevation. In 1904 there was only a west side porch. Today the porch is L-shaped, across the front and along the west side until it reaches the back building. It has a hipped roof carried on stock turned posts. It has a plain balustrade with access on the west side of the porch. A small back porch occupies the east bay of the south (rear) elevation.

PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW			
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	X.ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
1700-1799	ART	ENGINEERING	MUSIC	_THEATER
<del>X</del> 1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	TRANSPORTATION
_X1900-	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	OTHER (SPECIFY)
SPECIFIC DAT	ES between 1898 &	1904 BUILDER/ARCH	HITECT	

STATEMENT OF SIGNIFICANCE

This small house was built between 1898 and 1904 by Joseph and Ellin (Ellen) Harris on a lot they bought in 1898 from the estate of A. Preston Gilbert, Bel Air attorney, for \$500 (94/17). Gilbert's house was on Main Street next to this lot on Broadway. According to the <u>Harford Democrat</u> for September 3, 1897, he intended to build the next spring, but according to the same source for July 1, 1898, he moved into Mr. Heuer's new house (the Heuer-Corbin House, 611 N. Main). According to Miss Mary Harris Hall, niece of the Harrises, Heuer rented his new house until it had been paid for. (She also says that the house was originally ship-lap sided and the shingle was added later.) The house was built by 1904, because it appears on the Sanborn Map of that year.

The Harrises sold the property in 1907 to Ida W. Hunter for \$1000 (122/54). Mrs. Hunter was the daughter of Edwin H. Webster. She had purchased the Gilbert House, which came to be called the Lee House after her daughter Caroline (Mrs. John L. G. Lee). That house was demolished to make way for the Acme Market. The Harrises bought the house two doors to the east (53 E. Broadway) where they lived the rest of their lives. They left it to their nieces who own

Mrs. Hunter died in 1932. Her son-in-law, John L. G. Lee, bought both this house and the Home Place, but William Harlan, the executor of Mrs. Hunter's estate, neglected to convey before his death in 1942. Glasgow Archer, Jr., became the executor, but before the court case was decided, Mr. Lee died (1945). Mrs. Lee finally got title by 386/521. The owners are now Martha McCormick and her sister.

# 9 MAJOR BIBLIOGRAPHICAL REFERENCES

1904, 1930 Sanborn Maps Harford <u>Democrat</u>

### CONTINUE ON SEPARATE SHEET IF NECESSARY

# **MIGEOGRAPHICAL DATA** ACREAGE OF NOMINATED PROPERTY \_\_\_\_ VERBAL BOUNDARY DESCRIPTION This property occupies parcel #538 in the Town of Bel Air, 45' x 160' LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES STATE COUNTY STATE COUNTY **1** FORM PREPARED BY NAME / TITLE Marilynn Larew, Architectural Historian <u>19 October 1979</u> ORGANIZATION 838-8700 Town of Bel Air STREET & NUMBER TELEPHONE 39 Hickory Avenue CITY OR TOWN STATE Bel Air Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

MARYLAND HISTORICAL TRUST 21 STATE CIRCLE	SURVEY NUMBER: HA-1361			
SHAW HOUSE	NEGATIVE FILE NUMBER:			
ANNAPOLIS, MARYLAND 21401				
HISTORIC SITES SURVEY FIELD SHEET	UTM REFERENCES: Zone/Easting/Northing			
Individual Structure Survey Form				
	U.S.G.S. QUAD. MAP:			
	PRESENT FORMAL NAME:			
COUNTY: Harford TOWN: Bel Air	ORIGINAL FORMAL NAME: Harris House			
LOCATION:	PRESENT USE: rental unit			
43 E. Broadway	ORIGINAL USE: private residence			
COTION NAME:	ARCHITECT/ENGINEER:			
House	BUI LDER/CONTRACTOR:			
FUNCTIONAL TYPE: private residence	BOT LDERY CONTRACTOR.			
OWNER: Martha McCormick, c/o Cameron & ADDRESS: 30 Office Street Reed	PHYSICAL CONDITION OF STRUCTURE:			
ADDRESS: 30 Office Street Reed Bel Air, Md.	Excellent() Good(X)			
ACCESSIBILITY TO PUBLIC:	Fair() Poor() THEME: Architecture			
Yes() No() Restricted(X)	STYLE: Vernacular			
LEVEL OF SIGNIFICANCE:	DATE BUILT:			
Local(X) State() National()	Between 1898 & 1904			
GENERAL DESCRIPTION:				
Structural System  1. Foundation: Stone(x)Brick()Con				
2. Wall Structure	crete( )Concrete Block( )			
A. Wood Frame: Post and Beam()Balloon()				
B. Wood Bearing Masonry: Brick()Stone()Concrete()Concrete Block()				
C. Iron() D. Steel() E. Oth	er:			
3. Wall Covering: Clapboard()Boar	d and Batten() Wood Shingle(X) Shiplap() al() Aluminum() Asphalt Shingle()			
Brick Veneer()Stone Veneer(	ar( )Aruminum( )Asphart Shingle( )			
Bonding Pattern:	Other:			
4. Roof Structure				
A. Truss: Wood()Iron()Steel(	)Concrete( )			
B. Other: 5. Roof Covering: Slate() Wood Shingle() Apphala Shingle(Y) Share No. 16.				
5. Roof Covering: Slate()Wood Shingle()Asphalt Shingle(X)Sheet Metal() Built Up()Rolled()Tile()Other:				
6. Engineering Structure:				
7. Other:				
Appendages: Porches(X)Towers()Cupolas( Wings() Other:	)Dormers()Chimneys(X)Sheds()Ells(X)			
Roof Style: Gable(X)Hip()Shed()Flat()Mansard()Gambrel()Jerkinhead()				
Saw Tooth()With Monitor()With Bellcast()With Parapet()With False Front()				
Other: Number of Stories: 2½				
Number of Bays: 2	Entropeo Location, F. Broadway			
Approximate Dimensions: 20' x 30' Entrance Location: E. Broadway				
THREAT TO STRUCTURE:				
1 200.12 11.11.10516.				
Development(x)Deterioration() Mixed() Other:				
Alteration()Other:				

#### ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

L-shaped shingles added later front gable 3 part window 1/1, single pane, 1/1 windows 2/2 with wooden lentel double in front plain cap chimneys porch L-shaped (formerly only w side) hipped roof on stock turned posts, plain balustrade - access w side entrance in back building, w elev. back porch on e bay of s elev.

RELATED STRUCTURES: (Describe)

#### STATEMENT OF SIGNIFICANCE:

Harris family built it - before 1904

#### REFERENCES:

MAP: (Indicate North in Circle)



V mki

& Broadway

SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up()Densely Built Up()
Residential(X)Commercial(X)
Agricultural()Industrial()


Agricultural()Industrial()
Roadside Strip Development()
Other:


Marilynn Larew

RECORDED BY: Town of Bel Air

ORGANIZATION: 19 October 1979

DATE RECORDED:







HA = 1361 Harris House, 43 E. Broadway, Bil air 164 willer m Laver , 1979